
Second Floor



**Second-floor heating system is present but currently inoperable at the time of measurement.*
All measurements/calculations are believed to be reasonably correct within 5% of actual size, but are not warrented to be accurate. Measured by J. Zolzer License #337279